

Historical Well Records Search and Field Surve for Production Wells W1-3, W1-4, and W1-6 Lockheed Martin Corporation, Beaumont Site Beaumont, California



Historical Well Records Search and Field Surve for Production Wells W1-3, W1-4, and W1-6 Lockheed Martin Corporation, Beaumont Site Beaumont, California



## TABLE OF CONTENTS

1.0	INTR	ODUCT	ION	
			IPTION	
3.0	HIST	ORIC D	OCUMENT REVIEW AND RESULTS	1
	3.1	HISTO	DRIC AERIAL PHOTOGRAPH REVIEW AND RESULTS	4
	3.2	HISTO	DRIC DOCUMENT REVIEW	5
		3.2.1	Review of LMC-Provided Documents	5
		3.2.2	Review of Historic Environmental Investigation Reports	

## **APPENDICES**

Historic Aerial Photographs
Copies of Well Destotion Permits, W1-3 and W1-4
Copy of Department of Weat Resources Well Completion Record
Site Reconnaissance Photographs

## 1.0 INTRODUCTION

Historic information regarding Beaumont Site 1 (Sites) indicated that six production wells were used at various times to provide water for ranching and farming activities and subsequent research and development activities associated with rocket propulsiystems and ballistics. Of these six wells, three (W1-1, W1-2 and W1-5) have been properly destroyecording to State of California standards (Tetra Tech 2006). The status of the remaining three w(W1st-3, W1-4 and W1-6) remains unknown. This report documents the review of historic recordsoaisated with the Site and field reconnaissance to determine the present status and location of W1-3, W1-4 and W1-6.

## 2.0 SITE DESCRIPTION

The Beaumont Site 1, located south of Beaumont, California, covers 9,100 acres (Figure 1). The Site was purchased from the Government and various privatties in 1960 by the Lockheed Aircraft Company (LAC). From 1960 to 1963, the s7(ubkheed Aircraft Co)-ase2herc.98 13 AircmhP0.0019iorc.n 0.0004 Tw

Χ

BEAUMONT SITE 1 HISTORICAL WELL RECORDS

1980 Aerial Photograph It appears portions of the Site are beinsed for dry land agriculture again. All three wells can be observed in this photographu(Teitg A-5 and A-6). A power pole system has been installed north of Bedsprings Creek and south of nthair road that leads through the site (Figure A-5). The power poles trend from the east to the west and terminate at the site of W1-4 likely bringing power to W1-4 and subsequently across the unnamed drainage to W1-3.

1984 Aerial Photograph Little change to the site is observed in this aerial (Figure A-7). All three well locations are clearly observed.

1990 Aerial Photograph Potrero Creek has dramatically eroded the upland streambed associated with W1-6 and the area adjacent to this well (Figure A-8). W1-6 and associated features are no longer visible. Although the power pole line to W-4 is still visible, **those** ation of W1-4 and W1-3 are not visible (Figure A-9).

1995 Aerial Photograph Potrero Creek is even more eroded assigned in this aerial photograph. As with the 1990 aerial photograph of the site, W1-3,-4Wand W1-6 are not visible (Figures A-10 and A-11). The power pole line to the likely location of W1-4 is visible in this photograph.

2000 Aerial Photograph Little change at the site is observiend this 2000 aerial photograph (Figure A-12). Locations of W1-3, W1-4 and W1-6 are not visible.

2005 Aerial Photograph Little change at the site is observed in the 2005 aerial photograph (Figure A-13). Locations of W-3, W-4 and W-6 are not visible.

## 3.2 HISTORIC DOCUMENT REVIEW

The following section summarizes the documents reviewed as part of this evaluation.

## 3.2.1 Review of LMC-Provided Documents

As part of this task, database summaries of the doctsrtfeat have been produced as part of the various actions at Site 1 were reviewed. These databases provided to Tetra Tech from Lockheed Martin Corporation. In addition to the documents that rate Tech already had in their library, four other documents were identified as potential elevant to the historic record review for W1-3, W1-4 and W1-6 (Table 1).

These documents were requested frithe Lockheed Martin Corpdian repository. Of these four documents, the first two listed were received for review. A note was provided to Tetra Tech regarding the last two entries that indicated that these they had

In support of a 1990 investigati of the hydrogeologic conditions associated with Site 1, existing groundwater wells were sampled in Novembed December of 1989 and January 1990. During these rounds of sampling, only W1-3 was sampled (Table 2). It was reported in the 1990 report that W1-6 had a total depth of 155.2 feet bgs but could not be sampled its unsafe location on the steep edge of the stream channel of Potrero Creek.

**Radian Corporation** 

1992 Lockheed Propulsion Company Beaumont No Eacility Hydrogeologic Report

By 1991, erosion of the streambed had completely undermined W1-6. After 1992, W1-3 was no longer included in the sampling strategy for subsequent Sitevestigations. Well construction information for MW-40, a nearby monitoring well, shows that it waisled to a depth of 70 feet bgs and was screened from 46 feet to 66 feet bgs. Boring logs flow-40 show that the Mount Eden 78.46 735.3 Tm (W)Tj -6

Table 2 Summary of Results of EnvironmentaSamples from MW40, W1-3, and W1-6 (µg/).

Well Identities			
W1-3	W1-3	W1-3	
(Radian	(Radian	(Radian	
1986)	1989)	1990)	

Notes: The Analytical data was validated using the dia Analytical Service Data Export System using guidelines established by the erican Chemical Society.

BEAUMONT SITE 1 HISTORICAL WELL

## BEAUMONT SITE 1 HISTORICAL WELL RECORDSSEARCH AND FIELD SURVEY

 $FOR \ PRODU36.82\ T648\ Op8D dac8.460.001\ 0\ 0\ 102\ 279.66\ 7746.82\ Tm\ (B) Tj\ 0.0002810.001\ 0\ 0\ 1.98S02\ 458.91$ 

## 4.0 RESULTS OF FIELD RECONNAISSANCE

Field reconnaissance was conducted to determinate if three remaining production wells could be observed. An approximate location of the wells was tained from reports documenting past activities. Photographs and notes were taken to document values made during the field reconnaissance. The field reconnaissance of Site 1 was completed on the completed on the site reconnaissance may be found in Appendix Disodocument. A summary of activities and findings is presented below.

### 4.1.1 Well W1-3

Historic records for W1-3 place this well adjacentato unnamed drainage just east of monitoring well MW-40 (Figure 2). A power pole and concrete were found in the presumed location of W1-3 (Photographs 1 and 2). No obvious wellhead or assemble purtenances are visible in this location. A wellhead, (concrete apron and approximately entropy for well casing) were found in the streambed approximately 100 feet to the southeast of the presumed location of W1-3 (Photograph 3). No markings identifying the well were observe to based on proximity; it is likely that these items were associated with W1-3. Photograph 4 documents the likely location of W1-3 and MW-40.

### 4.1.2 Well W1-4

Historically, W1-4 has been identified as located **just**th of W1-3 on the opposite side of the unnamed drainage (Figure 2). No obvious wellhead or assted appurtenances are found in this area but some evidence exists to support this general location asittle for W1-4. Another power pole is located across the streambed from the power pole associated with W1-3 (Photograph 5). Review of historical aerial photographs indicates that at least by 1975, powers produced been placed parallel to the unnamed drainage with the terminal pole in the approximate location worker W1-4 would have been located. This pole was destroyed in the 2006 Esperanza fire and the elegized power line plus burnt debris subsequently removed. This power line likely brought electricity the well pump to W1-4 and the remaining power poles likely brought electricity to the well pump associated with W1-3 to the north. As with W1-3, a wellhead (concrete apron, approximately 5 feetwell casing) and a likely safety bollard are found some distance to the south of the presumed well location (Photographs 6 and 7).

### 4.1.3 Well W1-6

Well W1-6 was located during the reconnaissance witherstreambed of Potrero Creek (Figure 2). W1-6 and OW-4 were both located approximately 20 feeth the edge of the streambed bank. OW-4 is



## BEAUMONT SITE 1 HISTORICAL WELL RECORDSSEARCH AND FIELD SURVEY FOR PTw 10.001 0 7.9fH

## BEAUMONT SITE 1 HISTORICAL WELL RECORDSSEARCH AND FIELD SURVEY FOR PRODUCTION WELLS

## 5.2 RECOMMENDATIONS

### 5.2.1 Well W1-3

Records obtained from the County of Riverside indicate that W1-3 was destroyed as per State of California standards. No further action is recommended.

## 5.2.2 Well W1-4

Records obtained from the County of Riverside indicate that W1-4 was destroyed as per State of California standards. No further action is recommended.

## 5.2.3 Well W1-6

It does not appear either W1-6 or OW-04 have been properly destroyed according the State of California standards. Because of the proximity of the weells eroded stream bank neither of the wells can be safely worked on without excavating the face of the kbar shoring it up to prote TcCID 5 >.Rnor BApea Tc 0.

## 6.0 REFERENCES

## Leighton and Associates, Inc.

1984 Hydrogeologic Investigation for Wateesources Development, Potrero Creek, Riverside County, California

## Lockheed Engineering and Management Services Company, Inc.

1986 Aerial Photographic Analysis of the Besant and Crafton-Redlands Sites. Riverside and San Bernardino Counties, California, Phase I Report.

## Lockheed Martin Burbank Program Office

1995 December 1994 Water Level and Quality Repeaumont Test Site Facility Number 1, Beaumont California, Volume 1

## Riverside County Flood Control, County of Riverside

Aerial Image of Site 1, Beaumont, California

- 1948 Photograph Number 45
- 1962 Photograph Number 256
- 1974 Photograph Number 247 and 319
- 1980 Photograph Number 259 and 334
- 1984 Photograph Number 1359
- 1990 Photograph Number 46 and 48
- 1995 Photograph Number 44
- 2000 Photograph Number 45
- 2005 Photograph Number 45

## Radian Corporation

- 1986a Lockheed Propulsion Company Beaumont Test Facilities Historical Report
- 1986b Lockheed Propulsion Company Beaumont Test Facilities Preliminary Remedial Investigation
- 1989 Video Log of W1-3. Welenco, Inc.

### Radian Corporation


1990 Lockheed Propulsion Company Beaum Test Facilities Source and Hydrogeologic Investigation, Final

## **Radian Corporation**


1992 Lockheed Propulsion Company Beaumont No. 1 Facility Hydrogeologic Report

## Tetra Tech, Inc.


2006 Letter Report to Mr. Ju-tseng Liu, Detpræent of Toxic Substance Control entitled Abandonment of Former Production Wells Beataumont Site 1, Beaumont, California





X.\GIS\LOCKHEED 21617-01\1948.CDR	
	Beaumont Site 1
	Figure A-1 Historical 1948 Aerial Photograph  TETRATECH November 2007




Beaumont Site 1
Figure A-10 Historical 1995  November 2007














Photo 1 Likely location of W1-3. View to the southeast.




Photo 2 Likely location of W1-3. Note adjacent de-energized power pole that brought electricity to the pump for W1-3.




Photo 5 Likely location of W1-4. View to the northeast.




Photo 6 Likely wellhead and completion for W1-4 plus bollard.



Photo 7 W1-4 wellhead, completion plus about 5-feet of well casing. View to the southeast. Note power poles that likely supplied power to W1-4 and W1-3. Note adjacent pole to W1-4 destroyed in Esperanza Fire, 2006.





Photo 8 Location of W1-6 and OW-4. View from east side of Potrero Creek.

Photo	 13 2-inch di	istribution pi	ne in Potrero	Creek loca	ted west o	f W1-6.	
Photo	132-inch di	istribution pip	pe in Potrerc	Creek loca	ited west o	f W1-6.	
Photo	) 13 2-inch d	istribution pip	pe in Potrerc	Creek loca	ited west o	f W1-6.	
Photo	) 13 2-inch d	istribution pi	pe in Potrerc	Creek loca	ited west o	f W1-6.	
Photo	132-inch d	istribution pi	pe in Potrerc	Creek loca	ited west o	f W1-6.	
Photo	o 13 2-inch d	istribution pi	pe in Potrerc	Creek loca	ited west o	f W1-6.	
Photo	132-inch d	istribution pi	pe in Potrerc	Creek loca	ited west o	f W1-6.	
Photo	o 13 2-inch d	istribution pi	pe in Potrerc	Creek loca	ted west o	f W1-6.	
Photo	o 13 2-inch d	istribution pi	pe in Potrerc	Creek loca	ted west o	f W1-6.	
Photo	o 13 2-inch d	istribution pi	pe in Potrerc	Creek loca	ited west o	f W1-6.	
Photo	o 13 2-inch d	istribution pi	pe in Potrerc	Creek loca	ited west o	f W1-6.	
Photo	o 13 2-inch d	istribution pi	pe in Potrerc	Creek loca	ited west o	f W1-6.	
Photo	132-inch d	istribution pi	pe in Potrerc	Creek loca	ited west o	f W1-6.	
Photo	o 13 2-inch d	istribution pi	pe in Potrerc	Creek loca	ited west o	f W1-6.	

ı



•