Summit Soil &Water Conservation District 2795 Front Street, Suite D, Cuyahoga Falls, Ohio 44221
phone: 330.929.2871 fax: 330.929.2872
email: staff@summitswcd.org web: summitswcd.org

November 2, 2009

Mr. Matt Lascola, PE
GPD Associates
520 South Main Street
Akron, OH 44311

Subject: Site Inspection for Haley's Ditch Remediation! Restoration - Akron, Ohio

Dear Mr. Lascola,

Joan Hug-Anderson, from Summit SWCD, made a site inspection for sediment and erosion control at the above-referenced site on October 29,2009. Her comments follow:

STATUS OF THE SITE:

• Refresh stone on construction vehicle access points to reduce the amount ofmud tracked off site.
• Mud that is being tracked off site will need to be scraped off of the road and
returned to the site.

Please ensure that perimeter checks are conducted to identify and correct problems with all erosion control practices.

If you have any questions, please contact this office at (330) TUS