

ency

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

RE: AKRON AIRDOCK
31100203*AX
SUMMIT

of the Akron Airdock. The physical layout of the property. The Akron Airdock when in operation. As this facility does not discharge storm water is the only regulated facility. A multimillion dollar clean-up of the facility to remove PCB (Arochlor) contamination of the roof and sides

outlined the work that has been completed as the surrounding pavement is under an NPDES permit, 601, 602, and 603. Outfall 603 is represented by 603. Outfall 603 storm sewer is identified in

attached. If you should have any