Former Lockheed Martin French Road Facility Utica, New York Solvent Dock Area NYSDEC Site #6-20080321-5

Second Quarter 2019 Corrective Action Progress Report

Prepared for: Lockheed Martin Corporation 6801 Rockledge Drive MP CCT 246 Bethesda, MD 20817

Prepared by: Tetra Tech Inc. One Oxford Valley Road Langhorne, PA 19047

## Table of Contents

| PURPC | DSE2   |    |
|-------|--|----|
| 1.    | SUMMARY OF WORK COMPLETED DURING THE REPORTING PERIOD  | 2  |
| 2.    | SUMMARY OF FINDINGS MADE DURING THE REPORTING PERIOD   | .3 |
| 3.    | SUMMARY OF CHANGES MADE DURING THE REPORTING PERIOD  | .3 |
| 4.    | SUMMARY OF CONTACTS MADE WITH REPRESENTATIVES OF THE LOCAL COMMUNITY<br>AND PUBLIC INTEREST GROUPS DURING THE REPORTING PERIOD | 3  |
| 5.    | SUMMARY OF PROBLEMS ENCOUNTERED DURING THE REPORTING PERIOD  | 3  |
| 6.    | CHANGES IN PERSONNEL CONDUCTING OR MANAGING THE CORRECTIVE<br>MEASURES DURING THE REPORTING PERIOD                             | 3  |
| 7.    | SUMMARY OF WORK PLANNED FOR THE NEXT REPORTING PERIOD  | 3  |

## <u>ACRONYMS</u>

| DMR    | Discharge Monitoring Report                             |
|--------|---|
| FNPD   | Former Northern Perimeter Ditch                         |
| GCTS   | Groundwater Collection and Treatment System             |
| NYSDEC | New York State Department of Environmental Conservation |
| NYSDOH | New York State Department of Health                     |
| OM&M   | Operation, Monitoring and Maintenance                   |
| SPDES  | State Pollutant Discharge Elimination System            |
| SSDS   | Sub-Slab Depressurization System                        |
|        |   |